

# ScanPlus 1800

## Ordre

reset factory defaults



\46\42\60

predefined terminal selections - keyboard wedge - standard PC - QWERTY Norwegian



\41\4A\03\0F\60

keyboard wedge - preamble - compose: 1<Tab>BAR



\45\53\11\04\02\08\22\21\32\60

keyboard wedge - postamble - Enter (\*)



\45\54\04\02\01\60

Code 128 / EAN 128 - active



\41\5A\60